

Project Brief

## Arroyo Quemado Bridge

### Column Repair



Santa Barbara, CA, USA  
Spring 1999



Seismic retrofit of the crown columns for shear deficiencies and to increase column ductility. The Tyfo® Composites were chosen over the more traditional methods because of their low profile and ease of installation.

**Fyfe Co. LLC**

Nancy Ridge Technology Center

6310 Nancy Ridge Drive, Suite 103, San Diego, CA 92121-3209

**Tel:** 858.642.0694 **Fax:** 858.642.0947 **E-Mail:** [info@fyfeco.com](mailto:info@fyfeco.com) **www.fyfeco.com**