

Project Brief

## Prince Edward Island Steel Buoy Extending Service Life



PEI, Canada  
2000



Existing steel buoys were having to be serviced annually due to ice abrasions destroying the paint thus exposing the buoys to corrosion.



The buoys were wrapped with the Tyfo® SEH-51A System to extend their service life. After five years the retrofitted buoys have not required any additional maintenance.



**Fyfe Co. LLC**

Nancy Ridge Technology Center

6310 Nancy Ridge Drive, Suite 103, San Diego, CA 92121-3209

**Tel:** 858.642.0694 **Fax:** 858.642.0947 **E-Mail:** [info@fyfeco.com](mailto:info@fyfeco.com) **www.fyfeco.com**