

Project Brief

Koch Flare Pipe Retrofit



Texas, USA



A test precluded the installation to determine if the Tyfo® System could withstand high temperatures and pressure. Corrosion damage was heavy on the underside of the pipe and the need for temporary, conventional patching was required prior to the installation to contain the flare contents. This application was experimental and has great potential. Specific installation procedures were in place to ensure a successful application. A final layer of UV-resistant paint and Tyfo® FC/F fire protective coating was applied to ensure safety and long-term performance.

Fyfe Co. LLC

Nancy Ridge Technology Center

6310 Nancy Ridge Drive, Suite 103, San Diego, CA 92121-3209

Tel: 858.642.0694 **Fax:** 858.642.0947 **E-Mail:** info@fyfeco.com **www.fyfeco.com**